



Tek Ord



CHEMRING GROUP PLC

Dent Block Acceptance Test Susceptibility

Robert Savoyski
Andy Konst

© 2007 Chemring Group plc

The information in this document is the property of Chemring Group plc and may not be copied or communicated to a third party or used for any purpose other than that for which it is supplied without the express written consent of Chemring Group plc.


This information is given in good faith based upon the latest information available to Chemring Group plc, no warranty or representation is given concerning such information, which must not be taken as establishing any contractual or other commitment binding upon Chemring Group plc or any of its subsidiary or associated companies.

Failure to Detect Change


Investigation of a Change in Propagation
Reliability for Detonator/Booster Interface after
dent testing failed to detect the change

Overview

- MK 80 Bomb explosive train
- Simulation for testing




Test Set-up



History of Detonator Design

- Original: Plastic plug, epoxy seal, aluminum cup (AF 62A11810)
- Redesign: Glass header, hermetic solder seal, plated stainless steel cup
- Redesign reliability verified
- Witness block dent criteria confirmed

Detonator Construction



Problem

- Failure of Detonator to initiate Booster discovered during periodic interface testing
- Change in reliability of explosive transfer
- Historically: 30% margin on 99.9% reliability at 95% confidence
- Recently: 50% failures
- Detonator witness block testing demonstrated nominal detonator characteristics

Booster Propagation Data

<u>Det. Lot</u>	<u>Cup Thk</u>	<u>Booster Func. (Req'd. 5.9 mm)</u>	<u>Bruceton 50% Pt.(mm)</u>
99H001-001	0.0105		10.67
02H001-008	0.0105		11.04
06F003-001	0.0105	5/5	
07K003-005	0.0115	3/14	
08A003-006	0.0115	20/22	

Dent Data

<u>Lot</u>	<u>Avg Dent</u>	<u>Max Dent</u>	<u>Min Dent</u>	<u>Cup Thk</u>
99H001-001	0.020	0.021	0.019	0.0105
02H001-008	0.020	0.021	0.018	0.0105
04L002-002	0.021	0.022	0.020	0.0105
06F003-001	0.020	0.021	0.018	0.0105
07K003-005	0.022	0.025	0.021	0.0115
08A003-006	0.020	0.023	0.018	0.0115

Investigation of Variables

- Booster changes
- Detonator cup changes
- Lead Azide changes
- PETN changes
- Manufacturing process changes
- Test set-up changes

Detonator Construction Variables Testing

Function Results

<u>Parameter</u>	<u>8mm</u>	<u>9mm</u>	<u>10mm</u>
0.0115 cup end thk	1F/2S	3F/2S	2F
0.0105 cup end thk	-	4S	1S
Normal PETN qty	1F/2S	3F/5S	1F/1S
Increased PETN qty	-	1S	1F
Normal DLA qty	2S	3F/1S	1F
Increased DLA qty	-	1F/2S	1S
DLA	1F/1S	2F/5S	1F/1S
SPLA	1S	1F/1S	1F

Summation

- Detonator cup end thickness had greatest effect
- Flier plate transfer mechanism likely
- No other strong effects noted
- Another unidentified variable contributed to problem
- Additional increase in reliability desired

Booster Propagation Data

<u>Det Lot</u>	<u>Variable Tested</u>	Bruceton <u>50% Pt.(mm)</u>
99H001-001	Std Const	10.67
02H001-008	Std Const	11.04
S001	0.0105" cup thk	8.25
S002	18% inc DLA	8.75
S003	12% inc PETN	9.21
08M004-001	38% inc PETN	9.10

Effort to Increase Margin

- Increased LA: improved results
- Increased PETN quantity: greater effect

Final Conclusions

- Interface common to many explosive trains
- A small change in cup material thickness within drawing requirements had an unexpected change in explosive train performance
- Changes within normal tolerances may result in unexpected results