



Servicing **Hawker Vehicle Batteries** with Standard Battery Charging and Test Equipment



Mr. Fred Krestik **TARDEC**



2007 Joint Service Power Expo

Research, Development, and Engineering COMmand



The Hawker Battery



Hawker Armasafe Plus Battery NSN 6140-01-485-1472

Absorbent Glass Mat (AGM) technology



Research, Development, and Engineering COMmand



Recoverability



Hawker batteries have proven to be *highly* recoverable using standard charging equipment:

- Ft. Drum March 2006: >90% of Hawkers sent to DOL shop were successfully recovered using standard battery shop buss bar charging equipment.
- Ft. Hood May 2006, 2 pallets of Hawker batteries from DRMO were sent to TACOM for analysis:
 ≈90% were recovered using std. chargers/methods.



TB 9-6140-252-13



The technical information presented is taken from Technical Bulletin TB 0-6140-252-13 titled:

Field and Sustainment Maintenance and Recovery Procedures For Automotive HAWKER ARMASAFE Plus Battery NSN 6140-01-485-1472

Research, Development, and Engineering COMmand





Test Equipment:

- Multimeter or voltmeter: any type that reads in 1/10th volt increments. (Clamp-on ammeter function a plus.)
- 2. Battery analyzer (e.g. Midtronics or PulseTech) or heavy duty Load Tester.

Research, Development, and Engineering COMmand





Charging Equipment:

- Any charger with constant voltage output (rated at 12VDC or 12/24VDC) that can apply a charge to one or more batteries at a time using alligator clamps or NATO slave connector.
- Most modern chargers have settings/capabilities for AGM batteries.
- If in doubt, test charge voltage.
- Constant current chargers are not recommended.





To Verify Charger Output Voltage:

- 1. Attach charger to any fully charged (6TMF or Hawker) battery.
- 2. Apply power and wait a few minutes until ammeter reads ≈ 1 amp, and measure voltage across battery.
- 3. If voltage reading is > 15 VDC (> 30 VDC across series pair/NATO connector) do not use on Hawker batteries.

Research, Development, and Engineering COMmand



Pre-Charge Inspection



- Check top, sides, and bottom for damage. (i.e. cracks, dents, leaks, or swelling)
- 2. Check that the battery case and lid are sealed.
- 3. Make sure terminals aren't melted, bent or damaged.
- 4. Check for missing vent caps.

Mark and immediately dispose of batteries damaged as listed above.

Research, Development, and Engineering COMmand





Cell Vent Caps

Check that all vent caps are in place (flush) and do not appear to be elevated. Gently tap any elevated vent caps back into place and mark them with an "R" with a permanent marker. If a marked vent cap elevates again during charging or operation, dispose of the battery.

Research, Development, and Engineering COMmand





- 1. Clean corrosion from battery terminals with a wire brush.
- Using a voltmeter set to the lowest voltage range above 15 VDC, test the Open Circuit Voltage (OCV) and mark the OCV in pencil or chalk on the top of the battery.
- 3. If a battery analyzer is available, use it to determine if any internal damage exists. Many analyzers will not operate if the battery voltage is very low. If no reading is given or no internal damage is indicated, charge the battery for 24 hours and retest.





Charging Procedures Overviews:

- Buss Bar Charging Multiple Batteries
- Single Battery or "Roll Around" Chargers

WARNING:

The Charging Procedure Overviews that follow are overviews only. They do not include safety related information. Refer to TB 9-6140-252-13 for more detailed information and procedures.



Overview: Buss Bar Charging Procedures



Checklist summary:

- 1. Never mix battery types on a buss bar.
- 2. Group batteries by OCV ranges: 0 5.9V, 6.0 – 9.9V, 10V and up.
- 3. Set buss bar voltage between 14.7V and 15.2V.
- 4. Allow at least 10 Amps per battery, e.g. 100 Amp buss bar charger can support 10 batteries max.

Research, Development, and Engineering COMmand



Overview: Buss Bar Charging Procedures



- 1. Connect the batteries to the buss bars
- 2. Charge the batteries at least 24 to 48 hours
- 3. Check daily (recommend more frequently) for excessive heating, gassing, leaking, and proper voltage applied.
- 4. Immediately remove any battery that shows signs of excessive heat, gassing, leaking, or swelling during charging. Battery should be marked with date and "Charged Tested Bad", and disposed of.
- 5. Batteries are finished when charge current drops to approximately 1 Amp per battery.



Overview: Single Battery & "Roll Around" Chargers



- 1. Use only chargers that are compatible with AGM batteries. (Refer to charger instructions and the Charger Output Voltage test)
- 2. Set charger to appropriate settings for battery type and voltage. (Refer to charger instructions and instructions in the TB)
- 3. Connect charger to battery posts or NATO slave receptacle.
- 4. Turn on charger and monitor batteries for excessive heat and gassing during the charge cycle.



Overview: Single Battery & "Roll Around" Chargers



- 5. Some chargers automatically turn off at end of charge cycle. Some of these chargers require multiple cycles to fully charge batteries.
- 6. Batteries are finished when charge current drops to approximately 1 Amp.
- 7. "Rest" the batteries for 8 hours and test using a battery analyzer or load tester.
- 8. OCV of "rested" battery may also be used as an indicator of battery state of charge.







> 12.9 Volts OCV: 95% - 100% SOC
12.7 Volts OCV: about 80% SOC
12.5 Volts OCV: about 60% SOC
12.3 Volts OCV: about 50% SOC
12.1 Volts OCV: about 35% SOC
11.9 Volts OCV: about 20% SOC
11.7 Volts OCV: about 10% SOC
11.5 Volts OCV: about 5% SOC
< 11.4 Volts OCV: 0% SOC

If the battery hasn't "rested" sufficiently after charging, the voltage reading will be a bit higher than normal. If it hasn't "rested" sufficiently after discharging, the voltage reading may be a bit lower than normal.





Servicing **Hawker Vehicle Batteries** with Standard Battery Charging and Test Equipment





2007 Joint Service Power Expo

Research, Development, and Engineering COMmand



Thank-you!



For further information refer to

TB 9-6140-252-13

 Or contact:
 Boyd Dial
 or
 Fred Krestik

 DSN 786-2629
 DSN 786-8000
 586-753-2629
 586-574-8000

 dialb@tacom.army.mil
 krestikf@tacom.army.mil
 krestikf@tacom.army.mil

Research, Development, and Engineering COMmand