



Ricky Houghton

Ibis Tek

Hand Controller

- Why does the industry still deploy toy controllers?
- Mil-Spec versions exist
 - Deadman switches
 - Estop
 - Trigger Guards



UGV needs are different from UAV

- Video quality is critical
 - MPEG solutions are good for UAV, bad for UGV
 - Can't realistically target/shoot with 640x480 MPEG
 - Need infrastructure to support higher resolution
- Low latency is critical
 - Can't realistically shot a moving object with 250+ ms latency
 - Some currently deployed solutions are inadequate
 - MPEG memory require grow exponentially

Safety at the core

- It all starts with the education
 - Safety is not part of traditional software engineering training
 - Not sure it is part of electrical either
 - We need to fix this
- There are a lot of very bright people in robotics
 - Electrical, mechanical, software engineers
 - They want to solve interesting problems
 - Usually not safety
- Aerospace engineers and transportation engineers know safety, it is a culture thing